


COIN MECHANISM



NINE POINT GEAR WHEEL (may not be exact on your model)



Basic Machine Components (be sure to specify your machine height when ordering components)

- A - Screw Lock
- B - Cap
- C - Nut
- D - Spider Globe Retaining Ring/Gasket
- E - Globe
- F - Gasket
- G - Brush Off Plate
- M - Adjustable Dispensing Wheel
- H - Body
- I - Base Plate
- J - Coin Mechanism
- K - 9 Point Gear Wheel

Stand Components

- COLUMN 1 - Upper Support Column
- COLUMN 2 - Lower Support Column
- CENTER SUPPORT - Connection point for all 4 legs
- STAND LEG - 4 Required
- LEG BOLT and NUT - 4 ea. Required

